



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

September 5, 2007

Supervisor NO 24

**Mine Name:** Claim 35K

**Operator Name:** A G Hold, Associates (Jack Grover)

**Permit number:** S/041/013

**Inspection Date:** August 27, 2007

**Time:** 3:30 pm

**Inspector(s):** Lynn Kunzler, DOGM

**Other Participants:** None

**Mine Status:** Incactive

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Backfilling/Grading (trenches, pits, roads, highwalls,
7. Soils
8. Revegetation

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Check status of proposed reclamation work (as per meeting with Nephi Sandstone – Bruce Evans- in May of 2007, reclamation of this site was to begin within the next couple of weeks and be completed before the end of June, 2007.

#### Inspection Summary:

On May 23, 2007, I met with Bruce Evans of Nephi Sandstone (Jack Grover indicated that Nephi Sandstone would be doing the reclamation of this site). We reviewed the reclamation work that needed to be completed and it was stressed that the reclamation needed to be complete before the end of June (the next billing cycle). I had requested to be notified of when the work would begin so if possible I could be there to make sure all work was completed satisfactorily. Even though I was not contacted, I visited the site while in the area. Apparently no work has been done to date. Permit fees are now past due for two years.

Photos were taken.

#### Conclusions and Recommendations:

The operator needs to be contacted regarding payment of fees for two years (because the permit status is 'INS', no billing went out. If fees are not paid, appropriate enforcement action should be taken. If the site is not reclaimed by the end of October, 2007, the operator will need to go to the Board to explain why he should be allowed to leave the site open (it has been inactive for over 10 years).

**Inspector's Signature**

LK:pb

O:\M041-Sevier\S0410013-Claim35k\inspections\Insp-08272007.doc